



Model: See Affected Models	Jan. 23, 2024
Serial #: N/A	
Product Bulletin # TDS-248 Rev 1	

Top Drive T500 Gearbox Upgrade

Canrig has developed a design improvement for the Top Drive T500 gearbox, by upgrading the intermediate shaft, bearings and bearing retainer. This improvement is expected to increase the life of your equipment.

Affected Top Drive Models

- All T500 (aka 500-ESI-1000/1350) Top Drives manufactured before April 2023. These top drives will have a revision of the gearbox assembly as per one of the following part numbers:
 - 5005250-1
 - 5005250-2
 - 5005250-3
 - 5005250-HD
- All 750-ESI-1350 top drives.

Recommendation

It is strongly recommended to have this upgrade performed on affected top drives at the next Category IV recertification.

Reference

Work Instruction Canrig document # 5103918.

NOTICE

This work instruction is an internal Canrig document. Please contact RIGLINE 24/7™ or your Canrig Representative for more information.
